


BLEACHERS

a proud brand of FacillServ

Service & Repair Order Sheet

Facility Indoor & Outdoor Service & Repair Order Sheet

v the end column for Services you would like completed

Report #	Facility Area	Work to be performed	Price	v
19-18480SA	Capron ES, Main Gym	No additional service required	Ok	
	Service and Inspection: (4) backstops		\$ 970	
19-18485SA	Manchester ES, Main Gym	General service, check, adjust and tighten	\$ 1,207	
	Add BR 48" seat level aisle system with "P" handrails for safer egress <i>Note: Does not reduce step rise below 8" to meet egress code. Recommend (1) aisle minimum per bank.</i>		\$ 1,390ea.	
	Deliver (1) BR portable power system with receiver brackets installed at time of service		\$ 2,875	
19-18490SA	North Boone Upper ES, Main Gym	Service and Inspection	Completed	
	Hazard: Replace (10) cracked/damaged boards <i>at time of service:</i>		\$ 2,750*	
	Code: Install (2) BR Top Row End Rails to meet required* end rail height code		\$ 460	
	Add BR 48" cut-in foot level aisle system with "P" handrails for safer egress <i>Note: Recommend (1) aisle minimum per bank</i>		\$ 1,940ea.	
	BR Bulldog™ Automated Integral Power System: Install (6) BR Bulldog™ power units.		\$ 12,005	
	Discount: If completed at the same time as service, deduct:		(\$ 600)	
	Install (12) BR Top Deck Reinforcements - Patent #5369918 (ref. D BRPD-1)		\$ 3,418	
	Service and Inspection: (2) backstops		\$ 495	