

ATTACHMENT X-E

ATTACHMENT X-E: Approval of HLS Urgent Masonry and Concrete Repairs

Suggested Motion: Move to approve the HLS Urgent Masonry and Concrete Repairs

Recommended Action: Approve the motion.

It is recommended that we move forward with the urgent Health Life Safety masonry and concrete repairs, as identified by Wold Architects.

Manchester

Item X5 Exterior east wall shows a full height crack in masonry indicating a shift in the building wall

Middle School

Item X7 Exterior west wall shows a full height crack in masonry aligned with window lintel

Item X8 Exterior east wall shows a full height crack in masonry aligned with window lintel

Item E5 Electrical penetrations required to be closed for fire stop

Reference: Item 6 on the Capital Improvements HLS 2016-2017 List (Masonry Repairs-major) at MES and MS.

Architect estimate for investigation & repair: \$101,200