

Manchester Elementary School

Building Projects to done	Room #
Septic Tank is not working properly	Outside between office and gym
Locked safety double doors and "teller-style" window to office between doors	Lobby
Replace carpet on 2nd floor and office	All & Hall
Replace tile on main floor	Hall & lobby
Fix roof over upstairs closet between B&G's RR.	roof outside
Repave and level all blacktop	outside
Office remodel - new furniture and move nurse's desk into main area	Office
Door C does not regularly latch (this has been worked on several times)	Door C
Fire doors at bottom of back stairs don't close	by room 3
Restripe the gym floor	gym
Wooden doors under stage need replaced	gym
Playground wooden benches need replaced	playground
PA system in gym no longer works	gym
Stage Divider	gym
Playground security cameras	blacktop & Field
Office heat is not well regulated	Office
Cement and Railing outside boiler room (should happen this summer)	outside door B
Exhaust fan in room 10 (should happen this summer)	10

Upper Elementary School

Building Projects to done	Room #
Move/replace playground - currently not ADA compliant	
Paint gym - we are no longer the Jaguars	
Security camera in main lobby - wiring is in place when hallway cameras were installed last summer	
Install 6 remaining rooms with window AC units	106,121,111,117,115,000
paint lockers	
new classroom window blinds throughout	

Middle School

Building Projects to be done

Room #

Hallway lockers - Safety concern Option A: Replace lockers in East and west Hallways. Many are Option B - Reinforce lockers to prevent shifting on bases, file d	Hallway lockers in East and West Halls
Remodel of Main Office 1. Install new carpeting throughout 2. Replace counter tops including built-in file cabinets, drawers, and storage cabinets 3. Paint all walls 4. Install "teller-style" window for secretarial use with visitors to increase safety and limit access to building.	Main Office
Intallation of air exchange units for Room 118 and 119(Social Work Room) Currently there is no ventillation for these rooms. During warmer months these rooms become extremely warm and the air is stagnant. Classes are not held in the classroom in the afternoon due to conditions.	Classroom - 118 Social Work Room
Stage Curtains	Gym
Install Exterior cameras at all entrances and cafeteria courtyard	All Entrances
Boys' Locker room remodel (students no longer change for PE) 1. Remove all lockers and replace with new lockers for Athlete use only. Approximately 75-100 new lockers 2. Install cage for equipment storage 3. Install bench for game use during half time etc. 4. Install basic whiteboard for coach use	Boys' Locker room
Courtyard: create versatile space for possible outdoor classroom 1. Blacktop entire surface 2. Install additional benches around perimeter 3. Install planter boxes around perimeter 4. Install 10' fence with privacy slats and gate with lock	Courtyard
Parking lot needs to be resurfaced with the inclusion of speed bumps before and after front entrance	

High School

Building Projects to done	Room #
Replace all furniture with Flexible Seating Furniture	All Classrooms
Replace all restrooms with single-person restrooms	
Redesign main entrance so visitors need to walk through office to enter building when school is in session.	
Replace the Track	
Create a sports stadium that allows for football and soccer	
Replace the Baseball Field	
Replace the Softball Field	
Install Drinking Fountains in cafeteria so students do not need to leave the cafeteria to get a drink of water	
Replace all windows and doors with bullet proof glass	

Tech

Building Projects to done	Room and Building
Server room with proper space to work/move around and adequate cooling.	Middle School Main Server Room
Adequate security and space for working - Core switch	Poplar Grove Library
Adequate security and space for working. A/C.	Capron Switch - Nurses Office
Security cameras - Interior/Exterior	Poplar Grove
Security cameras - Interior/Exterior	Capron
Security cameras - Interior/Exterior	Manchester
Security cameras - Interior/Exterior (mostly exterior)	Upper Elementary
Security cameras - Interior/Exterior (mostly exterior)	Middle School
Security cameras - Interior/Exterior (better bus lot coverage)	District Office
Adequate security and space for working. A/C - Core switch	Manchester
Adequate security and space for working. A/C - Core switch	Upper Elementary
Area with proper ventilation for working with laser engraver.	Middle School Tech Room