

2019 Completed Summer Projects

High School

- Catch basin repairs
- Parking lot sealing
- Auxiliary gym roof repair
- Library underfloor drain leak repair
- Cafeteria table repairs
- Replaced softball backstops
- Cleaned windows on North side of school (eggs)

Manchester

- Entry window replacement
- Classroom window replacement
- Gym roof replacement (Did walk thru on 9/16/2019)
- Boiler room door replacement
- Gym exterior painting
- Boiler rebuild (tube replacement)
- Replenished playground mulch

Middle School

- Interior classroom painting
- Exterior soffit painting
- Parking lot repairs
- Music room carpet replacement
- Replaced hose bib on front of building
- Patched pot hole in parking lot
- Hung Viking banner

Capron

- Parking lot repairs
- Replaced library A/C
- Boiler rebuild (tube replacement)
- Patched pot holes in parking lot
- Fence at ball field
- Ground down crack at Door "G"

Poplar Grove

- Parking lot sealing
- Stripe "un-load zone " in parking lot (in process)